	Type	L#	Hits	Search Text	DBs	Time Stamp
	BRS	L2	0	((spiral with (conductor metal conductivity inductor)) and (resistivity resistance) and (area) and (coefficient with coupling)).clm.	US-PGPUB	2005/12/06 13:52
2	BRS	L3	0	((spiral with (conductor metal conductivity inductor)) and (resistivity resistance) and (coefficient with coupling)).clm.	US-PGPUB	2005/12/06 13:53
3	BRS	L4	1	((spiral with (conductor metal conductivity inductor)) and (resistivity resistance) and (coefficient)).clm.	US-PGPUB	2005/12/06 13:52
4	BRS	L5	72	((spiral with (conductor metal conductivity inductor)) and (resistivity resistance)).clm.	US-PGPUB	2005/12/06 13:53